

### MATERIAL SAFETY DATA SHEET

# BLUE

Version Number 1.0 Revision Date 06/24/2002 Page 1 of 7 Print Date 11/5/2011

### 1. PRODUCT AND COMPANY IDENTIFICATION

### POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012

NON-EMERGENCY TELEPHONE	: Product Stewardship (770) 271-5902			
Emergency telephone number	:	CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).		
Product name	:	BLUE		
Product code	:	CC10018228		
Chemical Name	:	Mixture		
CAS-No.	:	Mixture		
Product Use	:	Industrial Applications		

#### 2. COMPOSITION/INFORMATION ON HAZARDOUS INGREDIENTS

Components	CAS-No.	Weight %
Carbon black	1333-86-4	0.1 - 1
Mica	12001-26-2	10 - 30
Titanium dioxide	13463-67-7	10 - 30

### **3. HAZARDS IDENTIFICATION**

#### **EMERGENCY OVERVIEW**

This mixture has not been evaluated as a whole. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure.

### POTENTIAL HEALTH EFFECTS

<b>Routes of Exposure:</b>	: Inhalation, Ingestion, Skin contact
Acute exposure	
Inhalation Ingestion Eyes	<ul> <li>Resin particles, like other inert materials, can be mechanically irritating.</li> <li>May be harmful if swallowed.</li> <li>Resin particles, like other inert materials, are mechanically irritating to</li> </ul>
Skin	<ul><li>eyes.</li><li>Experience shows no unusual dermatitis hazard from routine handling.</li></ul>
Chronic exposure	: Refer to Section 11 for Toxicological Information.





BLUE	
Version Number 1.0 Revision Date 06/24/2002	Page 2 of 7 Print Date 11/5/2011
Medical Conditions Aggravated by Exposure:	: None known.
	4. FIRST AID MEASURES
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist, or in all cases of doubt, seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist, or in all cases of doubt, seek medical advice.
Eyes	: Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists seek medical attention.
	5. FIRE-FIGHTING MEASURES
Flash point	: Not applicable
Flammable Limits Upper explosion limit Lower explosion limit Autoignition temperature Suitable extinguishing media Special Fire Fighting Procedures Unusual Fire/Explosion	<ul> <li>Not applicable</li> <li>Not applicable</li> <li>Not relevant</li> <li>Carbon dioxide blanket, Water spray, dry powder, foam.</li> <li>Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.</li> <li>None</li> </ul>
Hazards	
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal. Refer to Section 13 of this MSDS for proper disposal methods.
	7. HANDLING AND STORAGE
Handling	: Take measures to prevent the build up of electrostatic charge. Heat only in areas with appropriate exhaust ventilation.

## MATERIAL SAFETY DATA SHEET



# BLUE

Mica       20 mppcf       PEL:       Total dust.       OSF         Titanium dioxide       10 mg/m3       Time Weighted Average (TWA):       Total dust.       ACC         Titanium dioxide       15 mg/m3       PEL:       Total dust.       OSH         Titanium dioxide       15 mg/m3       PEL:       Total dust.       OSH         PHYSICAL AND CHEMICAL PROPERTIES       9. PHYSICAL AND CHEMICAL PROPERTIES       OSH         Form       :       Solid       Evaporation rate       :       Not applicab         Appearance       :       Pellets       Specific Gravity       :       Not determin         Color       :       BLUE       Bulk density       :       Not establish         Odor       :       Very faint       Vapor pressure       :       Not applicab         Melting point/range       :       Not determined       Vapor density       :       Not applicab		10. 8	TABILITY AND RE	CACTIVIT	Y		
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra         Considerations       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Exposure time       Exposure type       Lis         Carbon black       3.5 mg/m3       Time Weighted Average       Total dust. as carbon       ACC         Mica       3 mg/m3       Time Weighted Average       Total dust.       ACC         Mica       20 mppcf       PEL:       Total dust.       ACC         Mica       20 mppcf       PEL:       Total dust.       ACC         (TWA):       Itanium dioxide       15 mg/m3       Time Weighted Average       Total dust.       ACC         (TWA):       Itanium dioxide       15 mg/m3       PEL:       Total dust.       ACC         (	Boiling Point:	: Not applicable pH : Not applicable					
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection : No personal respiratory protective equipment normally required.         Eye/Face Protection : Safety glasses with side-shields.         Hand protection : Protective gloves.         Skin and body protection : Long sleeved clothing.         Additional Protective : Safety shoes.         Measures         General Hygiene : Handle in accordance with good industrial hygiene and safety pra Considerations : Wash hands before breaks and at the end of workday.         Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)         Carbon black       3.5 mg/m3         Time Weighted Average Total dust. as carbon ACC (TWA):         Mica       3 mg/m3         Time Weighted Average Total dust. as carbon OSH/ black         Mica       3 mg/m3         Time Weighted Average Total dust.       ACC (TWA):         Mica       20 mppcf         PEL:       Total dust.       ACC (TWA):         Mica       10 mg/m3       Time Weighted Average Total dust.       ACC (TWA):         Mica       20 mppcf       PEL:       Total dust.       ACC (TWA):         Titanium dioxide       10 m							
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection : No personal respiratory protective equipment normally required.         Eye/Face Protection : Safety glasses with side-shields.         Hand protection : Protective gloves.         Skin and body protection : Long sleeved clothing.         Additional Protective : Safety shoes.         Measures         General Hygiene : Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)         Components       Value       Exposure time       Exposure type       Lis         Carbon black       3.5 mg/m3       Time Weighted Average       Total dust. as carbon       ACC         Mica       3 mg/m3       Time Weighted Average       Total dust.       ACC         Mica       3 mg/m3       Time Weighted Average       Total dust.       ACC         Mica       20 mppcf       PEL:       Total dust.       ACC         Mica       10 mg/m3       Time Weighted Average       Total dust.       ACC         Titanium dioxide       10 mg/m3       PEL:       T							
and contamination. Keep in a dry, cool place.         S. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection : No personal respiratory protective equipment normally required.         Eye/Face Protection : Safety glasses with side-shields.         Hand protection : Protective gloves.         Skin and body protection : Long sleeved clothing.         Additional Protective : Safety shoes.         Measures         General Hygiene : Handle in accordance with good industrial hygiene and safety pra         Considerations : Wash hands before breaks and at the end of workday.         Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)         Components Value Exposure time Exposure type Lis         Carbon black 3.5 mg/m3 Time Weighted Average Total dust. as carbon ACC (TWA):         Mica 3 mg/m3 Time Weighted Average Total dust. as carbon ACC (TWA):         Mica 20 mppcf       PEL: Total dust. ACC (TWA):         Mica 20 mppcf       PEL: Total dust. ACC (TWA):         Mica 10 mg/m3 Time Weighted Average Total dust. ACC (TWA):         Mica 10 mg/m3 Time Weighted Average Total dust. ACC (TWA):         Mica 10 mg/m3 Time Weighted Average Total dust. ACC (TWA):         Mica 10 mg/m3 Time Weighted Average Total dust. ACC (TWA):         Mica 10 mg/m3 Time Weighted Average Total dust.				-	•		
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra         Considerations       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Total dust. as carbon ACC (TWA):         Mica       3 mg/m3       Time Weighted Average Total dust. as carbon OSH/ black         Mica       20 mppcf       PEL:       Total dust.       ACC (TWA):         Mica       10 mg/m3       Time Weighted Average Total dust.       ACC (TWA):         Mica       20 mppcf       PEL:       Total dust.       ACC (TWA):         Mica       10 mg/m3       Time Weighted Average Total dust.       ACC (TWA):         Mica       10 mg/m3       Time Weighted Average Total dust.       ACC (TWA):							
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection : No personal respiratory protective equipment normally required.         Eye/Face Protection : Safety glasses with side-shields.         Hand protection : Protective gloves.         Skin and body protection : Long sleeved clothing.         Additional Protective : Safety shoes.         Measures         General Hygiene : Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)         Exposure limit(s)         Carbon black       3.5 mg/m3         Time Weighted Average Total dust. as carbon ACCO (TWA):         Mica       3 mg/m3         Time Weighted Average Total dust.       ACCO (TWA):         Mica       20 mppcf       PEL:       Total dust.       ACCO (TWA):         Mica       20 mppcf       PEL:       Total dust.       ACCO         Mica       10 mg/m3       Time Weighted Average Total dust.       ACCO		9. PHYSIC	CAL AND CHEMICA	AL PROP	ERTIES		
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra         Considerations       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Total dust. as carbon ACC (TWA):         Carbon black       3.5 mg/m3       PEL: Total dust. as carbon OSH/black         Mica       20 mppcf       PEL: Total dust.       ACC (TWA):         Mica       20 mppcf       PEL: Total dust.       ACC         Mica       10 mg/m3       Time Weighted Average       Total dust.       ACC	Titanium dioxide	15 mg/m3	PEL:		Total dust.	OSI	HA Z
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra         Considerations       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Exposure time       Exposure type       Lis         Carbon black       3.5 mg/m3       Time Weighted Average Total dust. as carbon ACC (TWA):       OSH/         Mica       20 mppcf       PEL:       Total dust.       ACC (TWA):	Titanium dioxide	10 mg/m3	-	erage	Total dust.	AC	CGIH
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra         Considerations       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       : Total dust. as carbon ACC (TWA):         Carbon black       3.5 mg/m3       PEL:       Total dust. as carbon ACC black         Mica       3 mg/m3       Time Weighted Average       Total dust. as carbon OSH/ black		20 mppcf	PEL:				SHA
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       :       No personal respiratory protective equipment normally required.         Eye/Face Protection       :       Safety glasses with side-shields.         Hand protection       :       Protective gloves.         Skin and body protection       :       Long sleeved clothing.         Additional Protective       :       Safety shoes.         Measures       :       Handle in accordance with good industrial hygiene and safety pra         Considerations       :       Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       :       Exposure time       Exposure type       Lis         Components       Value       Exposure time       Total dust. as carbon       ACC (TWA):         Carbon black       3.5 mg/m3       PEL:       Total dust. as carbon       OSH/	Mica	3 mg/m3	-	erage		AC	CGIH
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       :       No personal respiratory protective equipment normally required.         Eye/Face Protection       :       Safety glasses with side-shields.         Hand protection       :       Safety gloves.         Skin and body protection       :       Long sleeved clothing.         Additional Protective       :       Safety shoes.         Measures       :       Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures       :       Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       :       Components       Value       Exposure time       Exposure type       Lis	Carbon black	3.5 mg/m3		r		on OSI	HAZ
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       :       No personal respiratory protective equipment normally required.         Eye/Face Protection       :       Safety glasses with side-shields.         Hand protection       :       Protective gloves.         Skin and body protection       :       Long sleeved clothing.         Additional Protective       :       Safety shoes.         General Hygiene       :       Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures       :       Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       Value       Exposure time       Exposure type       Lis		5.5 mg/m3	-	cruge .			.011
and contamination. Keep in a dry, cool place. <b>8. EXPOSURE CONTROLS / PERSONAL PROTECTION</b> Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.         Exposure limit(s)       :			*				
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures       : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.	Carrier	<b>X7</b> - 1	Para	I	<b>D</b>		:
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         Measures       : Handle in accordance with good industrial hygiene and safety pra Wash hands before breaks and at the end of workday.         Engineering measures       : Heat only in areas with appropriate exhaust ventilation. Provide	Exposure limit(s)	1			ž		
and contamination. Keep in a dry, cool place. <b>8. EXPOSURE CONTROLS / PERSONAL PROTECTION</b> Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.         General Hygiene       : Handle in accordance with good industrial hygiene and safety pra	Engineering measures					on. Provid	le
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.         Skin and body protection       : Long sleeved clothing.         Additional Protective       : Safety shoes.							ractic
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.         Hand protection       : Protective gloves.		: S	afety shoes.				
and contamination. Keep in a dry, cool place.         8. EXPOSURE CONTROLS / PERSONAL PROTECTION         Respiratory protection       : No personal respiratory protective equipment normally required.         Eye/Face Protection       : Safety glasses with side-shields.	Skin and body protection	: L	ong sleeved clothing.				
and contamination. Keep in a dry, cool place.  8. EXPOSURE CONTROLS / PERSONAL PROTECTION  Respiratory protection : No personal respiratory protective equipment normally required.	Hand protection	: P:	rotective gloves.				
and contamination. Keep in a dry, cool place. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION	Eye/Face Protection	: S	afety glasses with side	-shields.			
and contamination. Keep in a dry, cool place.	Respiratory protection	: N	o personal respiratory	protective	equipment norma	lly require	d.
	8. I	EXPOSURE	CONTROLS / PERS	ONAL PF	ROTECTION		
	Storage					sture absor	ption



### MATERIAL SAFETY DATA SHEET

# BLUE

Version Number 1.0 Revision Date 06/24/2002		Page 4 of 7 Print Date 11/5/2011
Stability	:	Stable.
Hazardous Polymerization	:	Will not occur.
Conditions to avoid	:	Keep away from oxidizing agents and open flame. To avoid thermal decomposition, do not overheat.
Incompatible Materials	:	Incompatible with strong acids and oxidizing agents.
Hazardous decomposition products	:	Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.

### **11. TOXICOLOGICAL INFORMATION**

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

#### Toxicity Overview

This product contains the following components which in their pure form have the following characteristics:

CAS-No.	Chemical Name	Effect	Target Organ
1333-86-4	Carbon black	Systemic effects	Eyes, Respiratory system.
12001-26-2	Mica	Systemic effects	Respiratory system.
13463-67-7	Titanium dioxide	Systemic effects	Respiratory system.

#### LC50 / LD50

This product contains the following components which in their pure form have the following toxicity data:

CAS-No.	Chemical Name	Route	Value	Species
1333-86-4	Carbon black	Oral LD50	>15,400 mg/kg	rat
		Dermal LD50	> 3 gm/kg	rabbit

Carcinogenicity:

This product contains the following components which in their pure form have the following carcinogenicity data:

CAS-No.	Chemical Name	OSHA	IARC	NTP
1333-86-4	Carbon black	no	2B	no

IARC Carcinogen Classifications:

1 - The component is carcinogenic to humans.

2A - The component is probably carcinogenic to humans.

2B - The component is possibly carcinogenic to humans.

NTP Carcinogen Classifications:

1 - The component is known to be a human carcinogen.

2 - The component is reasonably anticipated to be a human carcinogen.

#### Additional Health Hazard Information:



#### MATERIAL SAFETY DATA SHEET

# **BLUE**

Version Number 1.0	Page 5 of 7
Revision Date 06/24/2002	Print Date 11/5/2011

Carbon black 1333-86-4 Carcinogenicity: Many inhalation toxicologists believe that the tumor response observed in the referenced rat studies is species specific and does not correlate to human exposure. However, the IARC evaluation in Monograph Volume 65, issued in April 1996 concluded that, "There is sufficient evidence in experimental animals for the carcinogenicity of carbon black". Based on this evaluation, along with their evaluation of inadequate evidence of carcinogenicity in humans, IARC's overall evaluation is that "Carbon Black is possibly carcinogenic to humans (Group 2B). Carbon Black has not been listed as a carcinogen by the National Toxicology Program (NTP) or the Occupational Safety and Health Administration (OSHA). The National Institute of Occupational Safety and Health (NIOSH) criteria document on carbon black recommends that only carbon black with PAH (polynuclear aromatic hydrocarbon) levels greater than 0.1% be considered suspect carcinogens.

	12. ECOLOGICAL INFORMATION
Persistence and degradability	: Not readily biodegradable.
Environmental Toxicity	: Chemicals are not readily available as they are bound within the matrix of the polymer.
Bioaccumulation Potential	: Chemicals are not readily available as they are bound within the matrix of the polymer.
Additional advice	: No data available.
	13. DISPOSAL CONSIDERATIONS
Product	: Like most thermoplastics the product can be recycled. Where possible, recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste materia has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT / CA TDG Classification	: Not regulated for transportation.
ICAO/IATA	: Not regulated for transportation.
IMO / IMDG	: Not regulated for transportation.
	15. REGULATORY INFORMATION
US Regulations:	
-	

5/7



### MATERIAL SAFETY DATA SHEET

BLUE	
Version Number 1.0 Revision Date 06/24/2002	Page 6 of 7 Print Date <i>11/5/2011</i>
OSHA Status :	Classified as hazardous based on components.
TSCA Status :	All components of this product are listed on the TSCA inventory or are exempt.
US. EPA CERCLA Hazardous Sub	stances (40 CFR 302)
Not applicable	
California Proposition : 65	This product does not contain a substance listed by California Prop 65.
Canadian Regulations:	
WHMIS Classification :	D2A
WHMIS Ingredient Disclosu	re List
CAS-No. 12001-26-2	
DSL :	Listed.
National Inventories:	
Australia AICS :	Listed.
China IECS :	Listed.
Europe EINECS :	Not determined.
Japan ENCS :	Not determined.
Korea KECI :	Listed.
Philippines PICCS :	Listed.
	16. OTHER INFORMATION

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.

### MATERIAL SAFETY DATA SHEET

# BLUE

Version Number 1.0 Revision Date 06/24/2002



Page 7 of 7 Print Date 11/5/2011