MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005 Page 1 of 6 Print Date 11/18/2011

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 8155 Cobb Center Drive, Kennesaw, GA 30152

Telephone Emergency telephone number	:	Product Stewardship (770) 590-3500 x.3563 CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	5050 501 LATEX THICKENER
Product code	:	FO00011006
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON REGULATED INGREDIENTS

Components	CAS-No.	Weight %
Potassium hydroxide (K(OH))	1310-58-3	1 - 5

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This product has not been evaluated as a whole for health effects. Information provided on the health effects of this product is based on individual components. In addition, some vapors or contaminants may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. See sections 8 and 11 for special precautions.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Skin contact, Inhalation, Ingestion
Acute exposure	
Inhalation	: Inhalation of airborne droplets may cause irritation of the respiratory tract.
Ingestion	: May be harmful if swallowed.
Eyes	: May cause eye/skin irritation.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.

PolyOne.

MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005 Page 2 of 6 Print Date 11/18/2011

	4. FIRST AID MEASURES
Inhalation	: Move to fresh air in case of accidental inhalation of vapors or fumes from overheating or combustion. When symptoms persist or in all cases of doubt seek medical advice.
Ingestion	: Never give anything by mouth to an unconscious person. Seek medical attention if necessary. Do not induce vomiting without medical advice.
Eyes	: Rinse immediately with plenty of water for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists seel medical attention.
	5. FIRE-FIGHTING MEASURES
Flash point	: No data available
Flammable Limits Upper explosion limit Lower explosion limit Autoignition temperature Suitable extinguishing media Special Fire Fighting Procedures Unusual Fire/Explosion Hazards	 No data available No data available No data available No data available carbon dioxide (CO2), water, foam, dry chemical. Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Cool closed containers exposed to fire with water spray Do not allow run-off from fire fighting to enter drains or water courses Burning dry latex produces dense black smoke with the possibility of toxic vapors. Residual latex material contained in empty drums may decompose when burned producing toxic or irritating fumes. Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Ensure response personnel are properly protected (see section 8 for respiratory or other protection guidelines.) Use caution as floors may be slippery.
Environmental precautions	: The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Soak up with inert absorbent material (e.g. sand, silica gel, acid binder universal binder, sawdust). Sweep up and shovel into suitable containers for disposal.

PolyOne.

MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005 Page 3 of 6 Print Date 11/18/2011

Prolonged heating may result in product degradation. Material may settle during storage. Careful mixing without introduction of air may be necessary before use. Storage : Containers which are opened must be carefully resealed and kept upright to prevent leakage. Keep in a dry, cool place. Keep from freezing and temperature extremes. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Respiratory protection : A respirator is normally not required for routine handling of product areas of good general ventilation and adequate local exhaust at processing equipment during routine operation. Airborne contamina levels should be maintained below the occupational exposure guidelines. Eye/Face Protection : Safety glasses with side-shields. Wear goggles or face shield during operations that present a splash potential. Hand protection : Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection. Additional Protective : Safety shoes. General Hygiene : Wash hands before breaks and immediately after handling the produc Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors.		7.	HANDLING AND STORA	GE	
upright to prevent leakage. Keep in a dry, cool place. Keep from freezing and temperature extremes. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Respiratory protection : A respirator is normally not required for routine handling of product areas of good general ventilation and adequate local exhaust at processing equipment during routine operation. Airborne contamina levels should be maintained below the occupational exposure guidelines. Eye/Face Protection : Safety glasses with side-shields. Wear goggles or face shield during operations that present a splash potential. Hand protection : Impervious gloves such as rubber or PVC Skin and body protection : Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection Additional Protective : Safety shoes. General Hygiene : Wash hands before breaks and immediately after handling the produc Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) Components Value Exposure time Exposure type List:	Handling	P	rolonged heating may result in ettle during storage. Careful r	n product degradation. N	Material may
Respiratory protection : A respirator is normally not required for routine handling of product areas of good general ventilation and adequate local exhaust at processing equipment during routine operation. Airborne contamina levels should be maintained below the occupational exposure guidelines. Eye/Face Protection : Safety glasses with side-shields. Wear goggles or face shield during operations that present a splash potential. Hand protection : Impervious gloves such as rubber or PVC Skin and body protection : Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection. Additional Protective : Safety shoes. General Hygiene : Wash hands before breaks and immediately after handling the product Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) Value Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH (K(OH))	Storage	u	pright to prevent leakage. Ke	ep in a dry, cool place.	
areas of good general ventilation and adequate local exhaust at processing equipment during routine operation. Airborne contamina levels should be maintained below the occupational exposure guidelines.Eye/Face Protection:Safety glasses with side-shields. Wear goggles or face shield during operations that present a splash potential.Hand protection:Impervious gloves such as rubber or PVCSkin and body protection:Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection.Additional Protective:Safety shoes.General Hygiene:Wash hands before breaks and immediately after handling the produc Handle in accordance with good industrial hygiene and safety practices.Engineering measures:Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors.Exposure limit(s)ValueExposure timeExposure typeList: Potassium hydroxide2 mg/m3Ceiling Limit Value: Total dust.ACGIH (K(OH))	8. E	XPOSURE	CONTROLS / PERSONAL	PROTECTION	
operations that present a splash potential. Hand protection : Impervious gloves such as rubber or PVC Skin and body protection : Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection. Additional Protective : Safety shoes. Measures : Wash hands before breaks and immediately after handling the produc Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH	Respiratory protection	a p le	reas of good general ventilation rocessing equipment during rocevels should be maintained be	on and adequate local exhoutine operation. Airborn	haust at ne contaminar
Skin and body protection : Long sleeved shirts and long pants are adequate for normal handling Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection. Additional Protective : Safety shoes. Measures : Wash hands before breaks and immediately after handling the produc Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) : Components Value Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH	Eye/Face Protection				shield during
Where operations present a splash or spill potential, employees shou wear chemically resistant clothing, boots, apron, gloves, and eye/fac protection. Additional Protective : Safety shoes. Measures : Safety shoes. General Hygiene : Wash hands before breaks and immediately after handling the product Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) : Components Value Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH	Hand protection	: I1	mpervious gloves such as rubb	per or PVC	
Measures : Wash hands before breaks and immediately after handling the product Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) : Components Value Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH	Skin and body protection	V W	Where operations present a spla year chemically resistant cloth	ash or spill potential, emp	ployees shoul
Considerations Handle in accordance with good industrial hygiene and safety practices. Engineering measures : Adequate ventilation and/or appropriate respiratory protection may also be necessary to minimize employee exposure to processing vapors. Exposure limit(s)	Additional Protective Measures	: S	afety shoes.		
also be necessary to minimize employee exposure to processing vapors. Exposure limit(s) Components Value Exposure time Exposure type List: Potassium hydroxide 2 mg/m3 Ceiling Limit Value: Total dust. ACGIH (K(OH))	General Hygiene Considerations	H	Iandle in accordance with goo		
ComponentsValueExposure timeExposure typeList:Potassium hydroxide2 mg/m3Ceiling Limit Value:Total dust.ACGIH(K(OH)) </td <td>Engineering measures</td> <td>a</td> <td>lso be necessary to minimize</td> <td></td> <td></td>	Engineering measures	a	lso be necessary to minimize		
Potassium hydroxide2 mg/m3Ceiling Limit Value:Total dust.ACGIH(K(OH))	Exposure limit(s)				
Potassium hydroxide2 mg/m3Ceiling Limit Value:Total dust.ACGIH(K(OH))	Components	Value	Exposure time	Exposure type	List:
9. PHYSICAL AND CHEMICAL PROPERTIES	Potassium hydroxide				
		9. PHYSI	CAL AND CHEMICAL PRO	OPERTIES	

MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005

Page 4 of 6 Print Date 11/18/2011

Form	:	liquid	Evaporation rate	:	Slower than Butyl Acetate
Appearance Color Odor Melting point/range Boiling Point: Water solubility	::	liquid NOT APPLICABLE Slight Not applicable Not established Completely miscible	Specific Gravity: Bulk density Vapor pressure Vapour density pH	:	Not determined Not applicable Not established Heavier than air. Not determined
		10. STABILITY AND R	EACTIVITY		
Stability		: Stable.			
Hazardous Polymerization		: Will not occur.			
Conditions to avoid		· Extramas of tamparatu	ro and direct sunlight	Koon	from froozing

Extremes of temperature and direct sunlight. Keep from freezing. Conditions to avoid

Incompatible Materials	:	Acids, metal salts, and solvents
------------------------	---	----------------------------------

: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen Hazardous decomposition (NOx), other hazardous materials, and smoke are all possible.

11. TOXICOLOGICAL INFORMATION

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

Toxicity Overview

products

This product contains the following components which in their pure form have the following characteristics:

CAS-No.	Chemical Name	Effect	Target Organ
1310-58-3	Potassium hydroxide	Systemic effects	Eyes, Skin.
	(K(OH))	-	
		Corrosive	Skin.
		toxic	Refer to LC50 / LD50 Data on
			MSDS

LC50 / LD50

This product contains the following components which, in their pure form, have the following toxicity data:

CAS-No.	Chemical Name	Route	Value	Species
1310-58-3	Potassium hydroxide	Oral LD50	273 mg/kg	rat
	(K(OH))			

12. ECOLOGICAL INFORMATION

Persistence and degradability

: No data available

Environmental Toxicity

: No data available

PolyOne.

MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005 Page 5 of 6 Print Date 11/18/2011

Bioaccumulation Potential	: No data available
Additional advice	: No data available
	13. DISPOSAL CONSIDERATIONS
Product	: Where possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification Proper Shipping Name: Technical Name: Hazard Class / Division UN Number Packing Group Label Required Hazardous Substance	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. Potassium hydroxide 8 UN3266 III 8 Not applicable
ICAO/IATA (air)	Refer to specific regulation.
IMO / IMDG (maritime)	Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: Classified as hazardous based on components.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.
US. EPA CERCLA Hazardous	Substances (40 CFR 302)
Not applicable	
California Proposition 65	: Not applicable

PolvOne

MATERIAL SAFETY DATA SHEET 5050 501 LATEX THICKENER

Version Number 1.3 Revision Date 05/24/2005 Page 6 of 6 Print Date 11/18/2011

SARA Title III Section 302 Extremely Hazardous Substance Not applicable						
SARA Title III Section 313 Toxic	c Chemicals:					
Not applicable Canadian Regulations:						
National Pollutant Release	Inventory (NPRI)					
Not applicable						
WHMIS Classification	WHMIS Classification :					
WHMIS Ingredient Disclo	WHMIS Ingredient Disclosure List					
CAS-No. 1310-58-3						
DSL	: All components of this product are on the Canadian Domestic Substances List (DSL) or are exempt.					
National Inventories:	National Inventories:					
Australia AICS	: Listed					
China IECS	: Listed					
Europe EINECS	: Not determined					
Japan ENCS	: Listed					
Korea KECI	: Listed					
Philippines PICCS	: Listed					
	16. OTHER INFORMATION					

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material when used in combination with any other materials and/or in any particular process or processing conditions.