PolyOne

## MATERIAL SAFETY DATA SHEET A11802 UV PPC

#### Version Number 1.0 Revision Date 02/20/2014

Page 1 of 6 Print Date 2/20/2014

POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012				
Telephone Emergency telephone number	:	1 (440) 930-1000 or 1 (866) POLYONE CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).		
Product name	:	A11802 UV PPC		
Product code	:	CC00080128		
Chemical Name	:	Mixture		
CAS-No.	:	Mixture		
Product Use	:	Industrial Applications		

Components	CAS-No.	Weight percent
1,6-Hexanediamine, N,N'-bis(2,2,6,6-	70624-18-9	5 - 10
tetramethyl-4-piperidinyl)-,polymer with		
2,4,6-trichloro-1,3,5-triazine, reaction		
products		

## **3. HAZARDS IDENTIFICATION**

#### **EMERGENCY OVERVIEW**

This mixture has not been evaluated as a whole. Information provided on the health effects of this product is based on individual components. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure.

### POTENTIAL HEALTH EFFECTS

<b>Routes of Exposure:</b>	: Inhalation, Ingestion, Skin contact
Acute exposure	
Inhalation	: Resin particles, like other inert materials, can be mechanically irritating.
Ingestion	: May be harmful if swallowed.
Eyes	: Resin particles, like other inert materials, are mechanically irritating to eyes.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.

**POLYONE CORPORATION** 

PolyOne.

# MATERIAL SAFETY DATA SHEET **A11802 UV PPC**

Version Number 1.0 Revision Date 02/20/2014 Page 2 of 6 Print Date 2/20/2014

Medical Conditions	: None known.
Aggravated by Exposure:	
	4. FIRST AID MEASURES
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases of doubt seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist or in all cases of doubt seek medical advice.
Eyes	: Rinse immediately with plenty of water, also under the eyelids, for a least 15 minutes. If eye irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists seek medical attention.
	5. FIREFIGHTING MEASURES
Flash point	: not applicable
Flammable Limits Upper explosion limit Lower explosion limit Auto-ignition temperature Suitable extinguishing media	<ul> <li>not applicable</li> <li>not applicable</li> <li>not applicable</li> <li>Carbon dioxide blanket, Water spray, Dry powder, Foam.</li> </ul>
Special Fire Fighting Procedures	: Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.
Unusual Fire/Explosion Hazards	: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should no be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal.
	7. HANDLING AND STORAGE



# MATERIAL SAFETY DATA SHEET **A11802 UV PPC**

ake measures to prevent the build up of electrostatic charge. Heat nly in areas with appropriate exhaust ventilation. Teep containers dry and tightly closed to avoid moisture absorption nd contamination. Keep in a dry, cool place. <b>CONTROLS/PERSONAL PROTECTION</b> To personal respiratory protective equipment normally required. afety glasses with side-shields rotective gloves ong sleeved clothing afety shoes fandle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. Ieat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
nly in areas with appropriate exhaust ventilation. Teep containers dry and tightly closed to avoid moisture absorption and contamination. Keep in a dry, cool place. <b>CONTROLS/PERSONAL PROTECTION</b> To personal respiratory protective equipment normally required. afety glasses with side-shields rotective gloves ong sleeved clothing afety shoes Iandle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. Ieat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
nd contamination. Keep in a dry, cool place. CONTROLS/PERSONAL PROTECTION To personal respiratory protective equipment normally required. afety glasses with side-shields rotective gloves ong sleeved clothing afety shoes Iandle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. Ieat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
lo personal respiratory protective equipment normally required. afety glasses with side-shields rotective gloves ong sleeved clothing afety shoes landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
afety glasses with side-shields rotective gloves ong sleeved clothing afety shoes landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
rotective gloves ong sleeved clothing afety shoes landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
ong sleeved clothing afety shoes landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
afety shoes landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
landle in accordance with good industrial hygiene and safety ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
ractice. Wash hands before breaks and at the end of workday. leat only in areas with appropriate exhaust ventilation. Provide ppropriate exhaust ventilation at machinery.
ppropriate exhaust ventilation at machinery.
CAL AND CHEMICAL PROPERTIES
Evapouration rate : Not applicable Specific Gravity : Not determined PIGMENT Bulk density : Not established faint Vapour pressure : not applicable determined Vapour density : not applicable pplicable pH : not applicable uble
STABILITY AND REACTIVITY
he product is stable if stored and handled as prescribed.
Vill not occur.
eep away from oxidizing agents and open flame. To avoid therma ecomposition, do not overheat.

PolvOn<u>e</u>

## MATERIAL SAFETY DATA SHEET A11802 UV PPC

#### Version Number 1.0 Revision Date 02/20/2014

Page 4 of 6 Print Date 2/20/2014

Hazardous decomposition products

: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.

## 11. TOXICOLOGICAL INFORMATION

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

**Toxicity Overview** 

This product contains the following components which in their pure form have the following characteristics:

	CAS-No.	Chemical Name	Effect	Target Organ
7	0624-18-9	1,6-Hexanediamine, N,N'-	Irritant	Eyes, Skin, Respiratory
		bis(2,2,6,6-tetramethyl-4-		system.
		piperidinyl)-,polymer with		
		2,4,6-trichloro-1,3,5-		
		triazine, reaction products		

LC50 / LD50

This product contains the following components which, in their pure form, have the following toxicity data:

CAS-No.	Chemical Name	Route	Value	Species
70624-18-9	1,6-Hexanediamine, N,N'- bis(2,2,6,6-tetramethyl-4- piperidinyl)-,polymer with 2,4,6-trichloro-1,3,5- triazine, reaction products	Oral LD50 Dermal LD50	> 2,000 mg/kg > 3,000 mg/kg	rat rat

### **12. ECOLOGICAL INFORMATION**

Persistence and degradability	:	Not readily biodegradable.
Environmental Toxicity	:	Chemicals are not readily available as they are bound within the polymer matrix.
Bioaccumulation Potential	:	Chemicals are not readily available as they are bound within the polymer matrix.
Additional advice	:	no data available
	13	3. DISPOSAL CONSIDERATIONS
Product	:	Like most thermoplastic plastics the product can be recycled. Where possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	:	Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification,

POLYONE CORPORATION



# MATERIAL SAFETY DATA SHEET **A11802 UV PPC**

sion Number 1.0 ision Date 02/20/2014	Page 5 Print Date 2/20/2
	transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification	: Not regulated for transportation.
ICAO/IATA	: Refer to specific regulation.
IMO/IMDG (maritime)	: Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: Classified as hazardous based on components.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.
US. EPA CERCLA Hazardo	ous Substances (40 CFR 302)
not applicable	
California Propositic 65	on : Not applicable
SARA Title III Section 302	Extremely Hazardous Substance
Unless specific chemicals ar	re identified under this section, this product is Not Applicable under this regula
SARA Title III Section 313	
SARA Title III Section 313	Toxic Chemicals:
SARA Title III Section 313	Toxic Chemicals:
SARA Title III Section 313 Unless specific chemicals ar Canadian Regulations:	Toxic Chemicals:
SARA Title III Section 313 Unless specific chemicals ar Canadian Regulations:	Toxic Chemicals: re identified under this section, this product is Not Applicable under this regula
SARA Title III Section 313 Unless specific chemicals ar Canadian Regulations: National Pollutant Re	re identified under this section, this product is Not Applicable under this regula elease Inventory (NPRI)

PolyOne

## MATERIAL SAFETY DATA SHEET A11802 UV PPC

Version Number 1.0 Revision Date 02/20/2014 Page 6 of 6 Print Date 2/20/2014

		Substances List (DSL) or are exempt.
National Inventories:		
Australia AICS	:	Not determined
China IECS	:	Not determined
Europe EINECS	:	Listed
Japan ENCS	:	Not determined
Korea KECI	:	Not determined
Philippines PICCS	:	Not determined
		16. OTHER INFORMATION

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.