

MATERIAL SAFETY DATA SHEET

COBALT BLUE

Version Number 1.0 Revision Date 04/01/2002 Page 1 of 5 Print Date 11/4/2011

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012

NON-EMERGENCY TELEPHONE	:	Product Stewardship (770) 271-5902
Emergency telephone number	:	CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	COBALT BLUE
Product code	:	CC10013519
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON HAZARDOUS INGREDIENTS

There are no known hazardous ingredients in this product.

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole. However, some vapors or contaminants may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. See sections 3 and 11 for special precautions.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	:	Inhalation, Skin contact, Ingestion	
Acute exposure			
Inhalation Ingestion Eyes Skin	:	Resin particles, like other inert materials, can be mechanically irritating. May be harmful if swallowed. Particulates, like other inert materials can be mechanically irritating. Experience shows no unusual dermatitis hazard from routine handling.	
Chronic exposure	:	Refer to Section 11 for Toxicological Information.	
Medical Conditions Aggravated by Exposure:	:	None known.	
		A FIDST AID MEASUDES	1

4. FIRST AID MEASURES

PolyOne.

MATERIAL SAFETY DATA SHEET

005			
COE	3AL I	BL	.UE

ion Number 1.0 sion Date 04/01/2002	Page 2 Print Date 11/4/2
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases or doubt seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist or in all cases of doubt seek medical advice.
Eyes	: Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists see medical attention.
	5. FIRE-FIGHTING MEASURES
Flash point	: Not applicable
Flammable Limits Upper explosion limit Lower explosion limit Autoignition temperature Suitable extinguishing media	 Not applicable Not applicable Not relevant Carbon dioxide blanket, Water spray, dry powder, foam.
Special Fire Fighting Procedures	: Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.
Unusual Fire/Explosion Hazards	: none
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal. Refer to Section 1 of this MSDS for proper disposal methods.
	7. HANDLING AND STORAGE
Handling	: Take measures to prevent the build up of electrostatic charge. Heat only in areas with appropriate exhaust ventilation.
Storage	: Keep containers dry and tightly closed to avoid moisture absorption and contamination. Keep in a dry, cool place.
8. EXPO	SURE CONTROLS / PERSONAL PROTECTION

MATERIAL SAFETY DATA SHEET



COBALT BLUE

sion Date 04/01/2002	Page 3 Print Date 11/4/2
Respiratory protection	: No personal respiratory protective equipment normally required. If dusty conditions occur wear appropriate respiratory protection.
Eye/Face Protection	: Safety glasses with side-shields.
Hand protection	: Protective gloves.
Skin and body protection	: Long sleeved clothing.
Additional Protective Measures	: Safety shoes.
General Hygiene Considerations	: Handle in accordance with good industrial hygiene and safety practice Wash hands before breaks and at the end of workday.
Engineering measures	: Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.
Exposure limit(s)	
9.	PHYSICAL AND CHEMICAL PROPERTIES
9. Form Appearance Color Odor Melting point/range Boiling Point: Water solubility	PHYSICAL AND CHEMICAL PROPERTIES: SolidEvaporation rate: Not applicable.: powder, granularSpecific Gravity: Not applicable.: BLUEBulk density: Not determined: Very faintVapor pressure: Not applicable: Not determinedVapor density: Not applicable: Not applicablepH: Not applicable: Insolubleinsoluble: Not applicable
Form Appearance Color Odor Melting point/range Boiling Point:	: SolidEvaporation rate: Not applicable.: powder, granularSpecific Gravity: Not applicable.: BLUEBulk density: Not determined: Very faintVapor pressure: Not applicable: Not determinedVapor density: Not applicable: Not applicablepH: Not applicable
Form Appearance Color Odor Melting point/range Boiling Point:	 Solid Evaporation rate : Not applicable. powder, granular Specific Gravity : Not applicable. BLUE Bulk density : Not determined Very faint Vapor pressure : Not applicable Not determined Vapor density : Not applicable Not applicable pH : Not applicable Insoluble
Form Appearance Color Odor Melting point/range Boiling Point: Water solubility	: SolidEvaporation rate: Not applicable.: powder, granularSpecific Gravity: Not applicable.: BLUEBulk density: Not determined: Very faintVapor pressure: Not applicable: Not determinedVapor density: Not applicable: Not applicablepH: Not applicable: InsolubleInsoluble: Not applicable
Form Appearance Color Odor Melting point/range Boiling Point: Water solubility Stability	: SolidEvaporation rate: Not applicable.: powder, granularSpecific Gravity: Not applicable.: BLUEBulk density: Not determined: Very faintVapor pressure: Not applicable: Not determinedVapor density: Not applicable: Not applicablepH: Not applicable: InsolubleInsoluble: Not applicable: Stable.: Stable.
Form Appearance Color Odor Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization	 Solid Evaporation rate : Not applicable. powder, granular Specific Gravity : Not applicable. BLUE Bulk density : Not determined Very faint Vapor pressure : Not applicable Not determined Vapor density : Not applicable insoluble pH : Not applicable Insoluble 10. STABILITY AND REACTIVITY Stable. Will not occur. To avoid thermal decomposition, do not overheat. Keep away from
Form Appearance Color Odor Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization Conditions to avoid	 Solid Evaporation rate : Not applicable. powder, granular Specific Gravity : Not applicable. BLUE Bulk density : Not determined Very faint Vapor pressure : Not applicable Not determined Vapor density : Not applicable Not applicable pH : Not applicable Insoluble 10. STABILITY AND REACTIVITY Stable. Will not occur. To avoid thermal decomposition, do not overheat. Keep away from oxidizing agents and open flame.

There are no known hazardous ingredients in this product.



MATERIAL SAFETY DATA SHEET

COBALT BLUE

ion Number 1.0 sion Date 04/01/2002	Page 4 Print Date 11/4/2
	12. ECOLOGICAL INFORMATION
Persistence and degradability	: Not readily biodegradable.
Environmental Toxicity	: Adverse ecological impact is not known or expected under normal use
Bioaccumulation Potential	: Not inherently biodegradable.
Additional advice	: No data available.
	13. DISPOSAL CONSIDERATIONS
Product	: Where possible, recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste materia has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. D.O.T. / CA T.D.G. Classification (Non-bulk ground)	: Not regulated for transportation.
ICAO/IATA	: Not regulated for transportation.
IMO / IMDG	: Not regulated for transportation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: Product is non-hazardous
TSCA Status	: All components of this product are listed on the TSCA inventory or ar exempt.
California Proposition 65	: This product does not contain a substance listed by California Prop 65
Canadian Regulations:	
WHMIS Classification	: Not controlled.
DSL	: Listed.

MATERIAL SAFETY DATA SHEET

COBALT BLUE

Version Number 1.0 Revision Date 04/01/2002 Page 5 of 5 Print Date 11/4/2011

vUne.

National Inventories:

Australia AICS	: Listed.
China IECS	: Listed.
Europe EINECS	: Not determined.
Japan ENCS	: Listed.
Korea KECI	: Listed.
Philippines PICCS	: Listed.

16. OTHER INFORMATION

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.