POLYONE CORPORATION

MATERIAL SAFETY DATA SHEET BLUE PEARL PP

Version Number 1.0 Revision Date 08/29/2007

Page 1 of 6 Print Date 11/30/2011

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012

Telephone Emergency telephone	:	Product Stewardship (770) 271-5902 CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	BLUE PEARL PP
Product code	:	CC10103567
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON REGULATED INGREDIENTS

Components	CAS-No.	Weight %
Titanium dioxide	13463-67-7	1 - 5
Mica	12001-26-2	5 - 10

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole. Information provided on the health effects of this product is based on individual components. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Inhalation, Ingestion, Skin contact
Acute exposure	
Inhalation Ingestion	Resin particles, like other inert materials, can be mechanically irritating.May be harmful if swallowed.
Eyes	: Resin particles, like other inert materials, are mechanically irritating to eyes.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.

POLYONE CORPORATION



MATERIAL SAFETY DATA SHEET **BLUE PEARL PP**

Version Number 1.0 Revision Date 08/29/2007 Page 2 of 6 Print Date 11/30/2011

Inhalation	:	Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases of doubt seek medical advice.
Ingestion	:	Do not induce vomiting without medical advice. When symptoms persist or in all cases of doubt seek medical advice.
Eyes	:	Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	:	Wash off with soap and plenty of water. If skin irritation persists seel medical attention.
		5. FIRE-FIGHTING MEASURES
Flash point	:	Not applicable
Elementela Lincita		
Flammable Limits Upper explosion limit		Not applicable
Lower explosion limit	:	Not applicable
Autoignition temperature	:	Not applicable
Suitable extinguishing media	:	Carbon dioxide blanket, Water spray, Dry powder, Foam.
Special Fire Fighting Procedures	:	Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.
Unusual Fire/Explosion Hazards	:	Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.
	6. A(CCIDENTAL RELEASE MEASURES
Personal precautions	:	Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	:	Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	:	Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal. Refer to Section 13 of this MSDS for proper disposal methods.
		7. HANDLING AND STORAGE
Handling	:	Take measures to prevent the build up of electrostatic charge. Heat only in areas with appropriate exhaust ventilation.
Storage	:	Keep containers dry and tightly closed to avoid moisture absorption

2/6

POLYONE CORPORATION

PolyOne.

MATERIAL SAFETY DATA SHEET **BLUE PEARL PP**

Version Number 1.0 Revision Date 08/29/2007

_

Page 3 of 6 Print Date 11/30/2011

Skin and body protection : Long sleeved clothing Additional Protective : Safety shoes Measures : Safety shoes General Hygiene : Handle in accordance with good industrial hygiene and safety procession of wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : : Maximum exhaust ventilation at machinery. Exposure limit(s) : : Maximum exhaust ventilation at machinery. Exposure limit(s) : : Maximum exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Image: Components Value Exposure time (TWA): Maximum exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Image: Components Value Exposure time (TWA): Maximum exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation. Provide approprint (TWA): Titanium	8. EXPOSURE CONTROLS / PERSONAL PROTECTION						
Hand protection : Protective gloves Skin and body protection : Long sleeved clothing Additional Protective : Safety shoes Measures : Safety shoes General Hygiene : Handle in accordance with good industrial hygiene and safety procession industrial hygiene industrial hygiene industrial hygiene industrial hygiene and safety procession industrial hygiene industria	tory protection	: N	lo personal respirato	ry protecti	ve equipment no	ormally r	equired.
Skin and body protection : Long sleeved clothing Additional Protective : Safety shoes Measures : Safety shoes General Hygiene : Handle in accordance with good industrial hygiene and safety procession of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : : Kespirable fraction. ACC Mica 3 mg/m3 Time Weighted Average (TWA): MX (TWA): MX (TWA): Titanium dioxide 10 mg/m3 Time Weighted Average (TWA): OSH OSH 10 mg/m3 Time Weighted Average (STEL): as Ti MX (STEL): Stort : Short Term Exposure Limit (STEL): OSH Stort : : Solid Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not determi Color : Color : : Slut Evaporation rate : Not applical Appearance : Not applical Protice : Not applical Specific Gravity : Not establis Odour <td< td=""><td>e Protection</td><td>: S</td><td>afety glasses with si</td><td>de-shields</td><td></td><td></td><td></td></td<>	e Protection	: S	afety glasses with si	de-shields			
Additional Protective :: Safety shoes Measures : Handle in accordance with good industrial hygiene and safety procession of the provide appropriate exhaust and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : : Exposure time Exposure type Li Mica 3 mg/m3 Time Weighted Average Respirable fraction. ACC Mica 3 mg/m3 Time Weighted Average MX verage ACC Titanium dioxide 10 mg/m3 Time Weighted Average as Ti MX verage 15 mg/m3 PEL: Total dust. OSH 20 mg/m3 Short Term Exposure Limit as Ti MX verage Short Term Exposure Limit as Ti MX verage Cord : Short Term Exposure Limit as Ti MX verage Cord : Short Term Exposure Limit as Ti MX verage Cord : Short Term Exposure Limit<	rotection	: P	rotective gloves				
Measures Image: Strategy and the strategy and	d body protection	: L	ong sleeved clothing	5			
Considerations Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) Exposure limit(s) Components Value Exposure time Exposure type Li Mica 3 mg/m3 Time Weighted Average Respirable fraction. ACC (TWA): 3 mg/m3 Time Weighted Average MX verage 10 mg/m3 Time Weighted Average ACC (TWA): 10 mg/m3 Time Weighted Average ACC 10 mg/m3 Time Weighted Average as Ti MX verage 10 mg/m3 Time Weighted Average as Ti MX verage 10 mg/m3 Time Weighted Average as Ti MX verage 10 mg/m3 Time Weighted Average as Ti MX verage 20 mg/m3 Short Term Exposure Limit as Ti MX verage 9. PHYSICAL AND CHEMICAL PROPERTIES Social Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not determined Color : BLUE Bulk density		: S	afety shoes				
appropriate exhaust ventilation at machinery. Exposure limit(s) Exposure time Exposure type Li Mica 3 mg/m3 Time Weighted Average (TWA): Respirable fraction. ACC 1 3 mg/m3 Time Weighted Average (TWA): MX of (TWA): MX of (TWA): ACC 1 10 mg/m3 Time Weighted Average (TWA): ACC ACC 1 15 mg/m3 PEL: Total dust. OSH 10 mg/m3 Time Weighted Average (TWA): as Ti MX of (TWA): 20 mg/m3 Short Term Exposure Limit (STEL): as Ti MX of (STEL): Solid Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not establis Odour : Wey faint Vapour pressure : Not applical Boiling Point: : Not applicable pH : Not applical							afety practice.
ComponentsValueExposure timeExposure typeLiMica3 mg/m3Time Weighted Average (TWA):Respirable fraction.ACC (TWA):3 mg/m3Time Weighted Average (TWA):MX 1Titanium dioxide10 mg/m3Time Weighted Average (TWA):ACC (TWA):Titanium dioxide10 mg/m3Time Weighted Average (TWA):ACC (TWA):15 mg/m3PEL:Total dust.OSH (TWA):10 mg/m3Time Weighted Average (TWA):as TiMX 1 (STEL):20 mg/m3Short Term Exposure Limit (STEL):as TiMX 1 (STEL):PHYSICAL AND CHEMICAL PROPERTIESForm: SolidEvaporation rate : Not applical AppearanceColor: BLUEBulk density: Not determi colorColor: BLUEBulk density: Not applical Bulk densityMelting point/range Boiling Point:: Not applicablePHYappical: Not applicablepH	ering measures					tilation.	Provide
Mica 3 mg/m3 Time Weighted Average (TWA): Respirable fraction. ACC 3 mg/m3 Time Weighted Average (TWA): MX MX Titanium dioxide 10 mg/m3 Time Weighted Average (TWA): MX Titanium dioxide 10 mg/m3 Time Weighted Average (TWA): ACC 15 mg/m3 PEL: Total dust. OSH 10 mg/m3 Time Weighted Average (TWA): as Ti MX 20 mg/m3 Short Term Exposure Limit (STEL): as Ti MX PHYSICAL AND CHEMICAL PROPERTIES Form : Solid Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not determing Odour : Very faint Vapour pressure : Not applical Melting point/range : Not determined Vapour density : Not applical Boiling Point: : Not applicable pH : Not applical	re limit(s)						
Image: Constraint of the second system of	omponents	Value	Exposure tin	ne	Exposure t	ype	List:
Image: constraint of the second se	3	3 mg/m3 Time Weighted Average		Respirable fra	action.	ACGIH	
Image: Constraint of the constraint	3	3 mg/m3 Time Weighted Average		verage			MX OEL
15 mg/m3 PEL: Total dust. OSH 10 mg/m3 Time Weighted Average (TWA): as Ti MX 20 mg/m3 Short Term Exposure Limit (STEL): as Ti MX 9. PHYSICAL AND CHEMICAL PROPERTIES Form : Solid Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not determinal Color : BLUE Bulk density : Not establis Odour : Very faint Vapour pressure : Not applical Melting point/range : Not determined Vapour density : Not applical Boiling Point: : Not applicable pH : Not applical	um dioxide 10	10 mg/m3 Time Weighted Av		verage			ACGIH
Image: constraint of the system of the sy	15				Total due	st.	OSHA Z1
(STEL): 9. PHYSICAL AND CHEMICAL PROPERTIES Form : Solid Evaporation rate : Not applical Appearance : pellets Specific Gravity : Not determin Color : BLUE Bulk density : Not establis Odour : Very faint Vapour pressure : Not applical Melting point/range : Not applicable pH : Not applicable		10 mg/m3 Time Weighted Aver		verage	as Ti		MX OEL
Form: SolidEvaporation rate: Not applicalAppearance: pelletsSpecific Gravity: Not determiColor: BLUEBulk density: Not establisOdour: Very faintVapour pressure: Not applicalMelting point/range: Not determinedVapour density: Not applicalBoiling Point:: Not applicablepH: Not applical	20	20 mg/m3 Short Term Exposure Limit		ıre Limit	as Ti		MX OEL
Appearance: pelletsSpecific Gravity: Not determinedColor: BLUEBulk density: Not establisOdour: Very faintVapour pressure: Not applicalMelting point/range: Not determinedVapour density: Not applicalBoiling Point:: Not applicablepH: Not applical	9. PHYSICAL AND CHEMICAL PROPERTIES						
Appearance: pelletsSpecific Gravity: Not determinedColor: BLUEBulk density: Not establisOdour: Very faintVapour pressure: Not applicalMelting point/range: Not determinedVapour density: Not applicalBoiling Point:: Not applicablepH: Not applical		· Sali	4	Fuence	ration rate	· Not	annlicable
Color: BLUEBulk density: Not establisOdour: Very faintVapour pressure: Not applicalMelting point/range: Not determinedVapour density: Not applicalBoiling Point:: Not applicablepH: Not applical	ance						
Odour: Very faintVapour pressure: Not applicatMelting point/range: Not determinedVapour density: Not applicatBoiling Point:: Not applicablepH: Not applicat		1					
Melting point/range: Not determinedVapour density: Not applicalBoiling Point:: Not applicablepH: Not applical					•		
Boiling Point: : Not applicable pH : Not applicable	point/range						11
					~		
Water solubility : Insoluble		: Insoluble					
10. STABILITY AND REACTIVITY		10. 9	STABILITY AND I	REACTIV	ITY		
Stability : Stable.	ý	: S	table.				

PolvUne

POLYONE CORPORATION

MATERIAL SAFETY DATA SHEET BLUE PEARL PP

Version Number 1.0 Revision Date 08/29/2007

Page 4 of 6 Print Date 11/30/2011

Hazardous Polymerization	:	Will not occur.
Conditions to avoid	:	Keep away from oxidizing agents and open flame. To avoid thermal decomposition, do not overheat.
Incompatible Materials	:	Incompatible with strong acids and oxidizing agents.
Hazardous decomposition products	:	Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.

11. TOXICOLOGICAL INFORMATION

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

Toxicity Overview

This product contains the following components which in their pure form have the following characteristics:

CAS-No.	Chemical Name	Effect	Target Organ
13463-67-7	Titanium dioxide	Systemic effects	Respiratory system.
12001-26-2	Mica	Systemic effects	Respiratory system.

Carcinogenicity

This product contains the following components which, in their pure form, have the following carcinogenicity data:

CAS-No.	Chemical Name	OSHA	IARC	NTP
13463-67-7	Titanium dioxide	no	2B	no

IARC Carcinogen Classifications:

1 - The component is carcinogenic to humans.

2A - The component is probably carcinogenic to humans.

2B - The component is possibly carcinogenic to humans.

NTP Carcinogen Classifications:

1 - The component is known to be a human carcinogen.

2 - The component is reasonably anticipated to be a human carcinogen.

12. ECOLOGICAL INFORMATION

Persistence and degradability	:	Not readily biodegradable.
Environmental Toxicity	:	Chemicals are not readily available as they are bound within the polymer matrix.
Bioaccumulation Potential	:	Chemicals are not readily available as they are bound within the polymer matrix.
Additional advice	:	No data available

POLYONE CORPORATION



MATERIAL SAFETY DATA SHEET **BLUE PEARL PP**

Version Number 1.0 Revision Date 08/29/2007 Page 5 of 6 Print Date 11/30/2011

Product	: Like most thermoplastic plastics the product can be recycled. Where possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification	: Not regulated for transportation.
ICAO/IATA (air)	: Refer to specific regulation.
IMO / IMDG (maritime)	: Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: Classified as hazardous based on components.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.
US. EPA CERCLA Hazardou	us Substances (40 CFR 302)
Not applicable	
California Proposition 65	n : Not applicable
SARA Title III Section 302 E	Extremely Hazardous Substance
Unless specific chemicals are	identified under this section, this product is Not Applicable under this regular

PolvOne

POLYONE CORPORATION

MATERIAL SAFETY DATA SHEET BLUE PEARL PP

Version Number 1.0	Page 6 of 6
Revision Date 08/29/2007	Print Date 11/30/2011

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation Canadian Regulations: National Pollutant Release Inventory (NPRI) NPRI ID# Chemical Name CAS-No. Weight % Phthalocyanine blue 147-14-8 0.10 - 1.00 71 WHMIS Classification : D2A WHMIS Ingredient Disclosure List CAS-No. 12001-26-2 DSL All components of this product are on the Canadian Domestic : Substances List (DSL) or are exempt. National Inventories: Australia AICS : Listed China IECS Listed ÷ **Europe EINECS** Listed : Japan ENCS Not determined : Korea KECI Listed : **Philippines PICCS** : Listed **16. OTHER INFORMATION** The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at

the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.