MATERIAL SAFETY DATA SHEET X HC 106151#SR-03606 Durastar MN631

Version Number 1.0 Revision Date 08/29/2013

Page 1 of 5 Print Date 8/29/2013

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012

Telephone Emergency telephone number	:	1 (440) 930-1000 or 1 (866) POLYONE CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	X HC 106151#SR-03606 Durastar MN631
Product code	:	EM10030244
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON INGREDIENTS

There are no known hazardous components above regulatory thresholds in this product.

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole. Information provided on the health effects of this product is based on individual components. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Inhalation, Ingestion, Skin contact
Acute exposure	
Inhalation Ingestion Eyes Skin	 Particulates, like other inert materials can be mechanically irritating. May be harmful if swallowed. Particulates, like other inert materials can be mechanically irritating. Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.

PolyOne.

MATERIAL SAFETY DATA SHEET X HC 106151#SR-03606 Durastar MN631

Version Number 1.0 Revision Date 08/29/2013 Page 2 of 5 Print Date 8/29/2013

		4. FIRST AID MEASURES
Inhalation	:	Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases of doubt seek medical advice.
Ingestion	:	Do not induce vomiting without medical advice. When symptoms persist or in all cases of doubt seek medical advice.
Eyes	:	Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	:	Wash off with soap and plenty of water. If skin irritation persists seek medical attention.
		5. FIREFIGHTING MEASURES
Flash point	:	not applicable
Flammable Limits		
Upper explosion limit		not applicable
Lower explosion limit	•	not applicable
Auto-ignition temperature	÷	not applicable
Suitable extinguishing media	:	Carbon dioxide blanket, Water spray, Dry powder, Foam.
Special Fire Fighting Procedures	:	Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.
Unusual Fire/Explosion Hazards	:	Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.
	6. A(CCIDENTAL RELEASE MEASURES
Personal precautions	:	Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	:	Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	:	Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal.
		7. HANDLING AND STORAGE
Handling	:	Take measures to prevent the build up of electrostatic charge. Heat only in areas with appropriate exhaust ventilation.
Storage	:	Keep containers dry and tightly closed to avoid moisture absorption and contamination. Keep in a dry, cool place.

<u>PolyOne</u>

MATERIAL SAFETY DATA SHEET X HC 106151#SR-03606 Durastar MN631

Version Number 1.0 Revision Date 08/29/2013

Page 3 of 5 Print Date 8/29/2013

Eye/Face Protection:SafetyHand protection:ProtectionSkin and body protection:Long sAdditional Protective:SafetyMeasures:SafetyGeneral Hygiene:Handle practiceConsiderations:Heat do	rsonal respiratory protective equipment normally required. a glasses with side-shields etive gloves sleeved clothing a shoes e in accordance with good industrial hygiene and safety ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
Hand protection : Protection Skin and body protection : Long state Additional Protective : Safety Measures : Safety General Hygiene : Handle Considerations : Heat of approp Engineering measures : Heat of approp Exposure limit(s) : Safety	e in accordance with good industrial hygiene and safety ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
Skin and body protection : Long s Additional Protective : Safety Measures : Handle General Hygiene : Handle Considerations : practic Engineering measures : Heat of approp Exposure limit(s) : Safety	sleeved clothing y shoes e in accordance with good industrial hygiene and safety ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
Additional Protective : Safety Measures : Handle General Hygiene : Handle Considerations practic Engineering measures : Heat of approp Exposure limit(s) : Safety	e in accordance with good industrial hygiene and safety ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
Measures General Hygiene : Handle Considerations : Heat of Engineering measures : Heat of approp Exposure limit(s)	e in accordance with good industrial hygiene and safety ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
Considerations praction Engineering measures : Heat of appropriation Exposure limit(s) : Heat of appropriation	ce. Wash hands before breaks and at the end of workday. only in areas with appropriate exhaust ventilation. Provide priate exhaust ventilation at machinery.
approp Exposure limit(s)	priate exhaust ventilation at machinery.
- · · ·	
There are no known hazardous components	1 1/ 4 111 4 1 /
there are no known nazardous components	
	s above regulatory unesholds in this product.
	AND CHEMICAL PROPERTIES
, inficial	AND CHEMICAL I KOI EKTIES
Form : solid	Evapouration rate : Not applicable
Appearance : pellets, SI	
Colour : BLACK	Bulk density : Not established
Ddour : very faint	
Melting point/range : Not deter	
Boiling Point: : not applic	1 2 11
Water solubility : insoluble	F F FF
10. STAI	BILITY AND REACTIVITY
Stability : The pr	roduct is stable if stored and handled as prescribed.
Hazardous Polymerization : Will n	tot occur.
Conditions to avoid : To avo	oid thermal decomposition, do not overheat.
ncompatible Materials : Strong	g acids, oxidizing and reducing agents
	n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen), other hazardous materials, and smoke are all possible.
11. TOXIC	OLOGICAL INFORMATION

PolyOne.

MATERIAL SAFETY DATA SHEET X HC 106151#SR-03606 Durastar MN631

Version Number 1.0 Revision Date 08/29/2013 Page 4 of 5 Print Date 8/29/2013

Persistence and degradability	: Not readily biodegradable.
Environmental Toxicity	: Chemicals are not readily available as they are bound within the polymer matrix.
Bioaccumulation Potential	: Chemicals are not readily available as they are bound within the polymer matrix.
Additional advice	: not applicable
	13. DISPOSAL CONSIDERATIONS
Product	: Like most thermoplastic plastics the product can be recycled. Where possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification	: Not regulated for transportation.
ICAO/IATA	: Refer to specific regulation.
IMO/IMDG (maritime)	: Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: There are no known hazardous components above regulatory thresholds in this product.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.
US. EPA CERCLA Hazardous	Substances (40 CFR 302)
not applicable	

PolvOne

MATERIAL SAFETY DATA SHEET X HC 106151#SR-03606 Durastar MN631

Version Number 1.0 Revision Date 08/29/2013 Page 5 of 5 Print Date 8/29/2013

California Proposition : Not applicable 65

SARA Title III Section 302 Extremely Hazardous Substance

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

SARA Title III Section 313 Toxic Chemicals:

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

Canadian Regulations:

National Pollutant Release Inventory (NPRI)

not applicable

WHMIS Classification	:	Not controlled.
DSL	:	All components of this product are on the Canadian Domestic Substances List (DSL) or are exempt.
National Inventories:		
Australia AICS	:	Not determined
China IECS	:	Not determined
Europe EINECS	:	Listed
Japan ENCS	:	Not determined
Korea KECI	:	Not determined
Philippines PICCS	:	Not determined

16. OTHER INFORMATION

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.