

MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

Version Number 1.0 Revision Date 06/11/2002 Page 1 of 6 Print Date 11/4/2011

### 1. PRODUCT AND COMPANY IDENTIFICATION

#### POLYONE CORPORATION 2700 Papin Street, St. Louis, MO 63103

NON-EMERGENCY TELEPHONE	:	Product Stewardship, (314) 771-1800
Emergency telephone number	:	CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	SW BLUE ADDITIVE
Product code	:	FO00007877
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

#### 2. COMPOSITION/INFORMATION ON HAZARDOUS INGREDIENTS

Components	CAS-No.	Weight %
Titanium dioxide	13463-67-7	30 - 60

#### **3. HAZARDS IDENTIFICATION**

#### **EMERGENCY OVERVIEW**

This mixture has not been evaluated as a whole for health effects. Information provided on health effects of this product is based on the individual components. However, some vapors or contaminants may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. See sections 8 and 11 for special precautions.

#### POTENTIAL HEALTH EFFECTS

<b>Routes of Exposure:</b>	: Inhalation, Skin contact, Ingestion
Acute exposure	
Inhalation	: Inhalation of airborne droplets may cause irritation of the respiratory tract.
Ingestion	: May be harmful if swallowed.
Eyes	: May cause eye/skin irritation.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.



MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

sion Number 1.0 ision Date 06/11/2002	Page 2 Print Date 11/4/2
	4. FIRST AID MEASURES
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist, or in all cases of doubt, seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist, or in all cases of doubt, seek medical advice.
Eyes	: Rinse immediately with plenty of water for at least 15 minutes. If ey irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists see medical attention.
	5. FIRE-FIGHTING MEASURES
Flash point	: No data available.
Flammable Limits Upper explosion limit Lower explosion limit Autoignition temperature Suitable extinguishing media	<ul> <li>No data available.</li> <li>No data available.</li> <li>Not applicable.</li> <li>Carbon dioxide blanket, dry powder, foam, Water spray.</li> </ul>
Special Fire Fighting Procedures	: Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants.
Unusual Fire/Explosion Hazards	<ul> <li>May emit Hydrogen Chloride (HCl) or Carbon Monoxide (CO) unde fire conditions.</li> </ul>
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Soak up with inert absorbent material (e.g. sand, silica gel, acid binder universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods.
	7. HANDLING AND STORAGE
Handling	: Heat only in areas with appropriate exhaust ventilation. Processing fume condensates may contain combustible or toxic residue. Periodically clean hoods, ducts, and other surfaces to minimize



### MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

Keep contain and contamin E CONTROL Under normal Safety glasses Protective glo Long sleeved Safety shoes. Handle in acc Wash hands t Heat only in a appropriate ex Exp 3 Time We 3	LS / PERSONAL I handling condit s with side-shield oves. clothing.	y closed to avoid r cool dry place. <b>PROTECTION</b> tons a respirator is s. d industrial hygier at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	not req not req kday. ilation.	quired.
and contamin <b>E CONTROL</b> Under normal Safety glasses Protective glo Long sleeved Safety shoes. Handle in acc Wash hands the Heat only in a appropriate est <u>Exp</u> 3 Time We 3	LS / PERSONAL LS / PERSONAL I handling condit is with side-shield oves. clothing. cordance with good before breaks and areas with appropriate the state of the shield over the state of the shield over the state of the shield over the	cool dry place. <b>PROTECTION</b> ions a respirator is         s.         d industrial hygien         at the end of work         riate exhaust vent         at machinery.         Exposure ty         Total dus         Total dus	not req not req kday. ilation.	quired. safety practice Provide List: ACGIH
Under norma Safety glasses Protective glo Long sleeved Safety shoes. Handle in acc Wash hands the Heat only in a appropriate est <u>Exp</u> 3 Time We (3	l handling condit s with side-shield oves. clothing. cordance with goo before breaks and areas with approp xhaust ventilation osure time eighted Average TWA): PEL:	d industrial hygien at the end of worl riate exhaust vent at machinery.	not req me and s kday. ilation.	afety practice Provide List: ACGIH
Safety glasses Protective glo Long sleeved Safety shoes. Handle in acc Wash hands t Heat only in a appropriate es <u>Exp</u> 3 Time We (3	s with side-shield oves. clothing. cordance with goo pefore breaks and areas with approp xhaust ventilation <u>ossure time</u> pighted Average (TWA): PEL:	s. d industrial hygien at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	ne and s kday. ilation. ypet.	afety practice Provide List: ACGIH
Protective glo Long sleeved Safety shoes. Handle in acc Wash hands t Heat only in a appropriate ex <u>Exp</u> 3 Time We (3	oves. clothing. cordance with goo before breaks and areas with approp xhaust ventilation <u>oosure time</u> sighted Average TWA): PEL:	d industrial hygier at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	kday. ilation. ypet.	Provide List: ACGIH
Long sleeved Safety shoes. Handle in acc Wash hands t Heat only in a appropriate ex <u>Exp</u> 3 Time We 3	clothing. cordance with goo before breaks and areas with approp xhaust ventilation osure time eighted Average TWA): PEL:	at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	kday. ilation. ypet.	Provide List: ACGIH
Safety shoes. Handle in acc Wash hands t Heat only in a appropriate e: <u>Exp</u> 3 Time We (3	cordance with goo pefore breaks and areas with approp xhaust ventilation osure time eighted Average TWA): PEL:	at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	kday. ilation. ypet.	Provide List: ACGIH
Handle in acc Wash hands t Heat only in a appropriate ex <u>Exp</u> 3 Time We 3	cordance with goo before breaks and areas with approp xhaust ventilation bosure time eighted Average (TWA): PEL:	at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	kday. ilation. ypet.	Provide List: ACGIH
Wash hands to Heat only in a appropriate ex Exp 3 Time We 3	opefore breaks and areas with approp xhaust ventilation osure time sighted Average (TWA): PEL:	at the end of worl riate exhaust vent at machinery. Exposure ty Total dus Total dus	kday. ilation. ypet.	Provide List: ACGIH
appropriate exp Exp 3 Time We 3	osure time eighted Average TWA): PEL:	at machinery. Exposure ty Total dus Total dus	ype t.	List: ACGIH
3 Time We	eighted Average TWA): PEL:	Total dus Total dus	t.	ACGIH
3 Time We	eighted Average TWA): PEL:	Total dus Total dus	t.	ACGIH
3	TWA): PEL:	Total dus		
			t.	OSHA Z1
SICAL AND C	CHEMICAL PR	OPERTIES		
quid	Evap	oration rate	: Not	testablished
scous, Liquid		fic Gravity		t determined
LUE		density		applicable.
ery faint		r pressure		determined
ot applicable	-	r density		t determined
ot applicable	pH		: Not	t applicable.
imiscible				
. STABILITY	Y AND REACTI	VITY		
Stable.				
Will not occu	ır.			
Keep away fr			ie. To a	avoid thermal
	Stable. Will not occu Keep away fr	<b>0. STABILITY AND REACTI</b> Stable. Will not occur.	<b>0. STABILITY AND REACTIVITY</b> Stable. Will not occur. Keep away from oxidizing agents and open flam	<b>0. STABILITY AND REACTIVITY</b> Stable. Will not occur. Keep away from oxidizing agents and open flame. To a



MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

Version Number 1.0 Revision Date 06/11/2002	Page 4 of 6 Print Date 11/4/2011
Incompatible Materials	: Incompatible with strong acids and oxidizing agents. Avoid contact with acetal homopolymers and acetal copolymers during processing.
Hazardous decomposition products	: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), hydrogen chloride (HCl), other hazardous materials, and smoke are all possible. Prolonged heating may result in product degradation. As a general rule of thumb, degradation begins to occur after one hour at 177 °C (350 °F), after 10 minutes at 204 °C (400 °F), and within 5 minutes at 232 °C (450 °F).
	11. TOXICOLOGICAL INFORMATION
	aluated as a whole for health effects. Exposure effects listed are based on existing components which comprise the mixture.

Toxicity Overview

This product contains the following components which in their pure form have the following characteristics:

13463-67-7 Titaniu		m dioxide	Systemic effects	Respiratory system.
		12. ECOLOGIO	CAL INFORMATION	1
Persistence and degrad	lability	: Not readily b	iodegradable.	
Environmental Toxicit	У	: Environmenta whole.	al toxicity has not been	established for this mixture as a
Bioaccumulation Poter	ntial	: No data avail	able.	
Additional advice		: No data avail	able.	
		13. DISPOSAL	CONSIDERATIONS	5
Product		generator of v classification	waste material has the r	ed to disposal or incineration. Th esponsibility for proper waste posal in accordance with nd local regulations.
Contaminated packagi	ng	has the respon	nsibility for proper was in accordance with app	e. The generator of waste materia te classification, transportation licable federal, state/provincial
		14. TRANSPO	<b>RT INFORMATION</b>	
U.S. D.O.T. / CA T.D. Classification (Non-bu ground)		: Not regulated	for transportation.	



### MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

sion Number 1.0 ision Date 06/11/2002		Page 5 of 6 Print Date 11/4/2011
ICAO/IATA	:	Not regulated for transportation.
IMO / IMDG	:	Not regulated for transportation.
	15	. REGULATORY INFORMATION
US Regulations:		
OSHA Status	:	Classified as hazardous based on components.
TSCA Status	:	All components of this product are listed on the TSCA inventory or are exempt.
US. EPA CERCLA Hazardous	Sub	stances (40 CFR 302)
Not applicable		
California Proposition 65	:	This product does not contain a substance listed by California Prop 65.
Canadian Regulations:		
WHMIS Classification	:	D2B
WHMIS Ingredient Disc	losu	re List
CAS-No. 1333-86-4		
DSL	:	Listed.
National Inventories:		
Australia AICS	:	Listed.
China IECS	:	Listed.
Europe EINECS	:	Listed.
Japan ENCS	:	Not determined.
Korea KECI	:	Listed.
Philippines PICCS	:	Listed.



MATERIAL SAFETY DATA SHEET

# SW BLUE ADDITIVE

Version Number 1.0 Revision Date 06/11/2002 Page 6 of 6 Print Date 11/4/2011

### **16. OTHER INFORMATION**

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.