

MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Version Number 1.0 Revision Date 09/10/2002 Page 1 of 7 Print Date 11/6/2011

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 2700 Papin Street, St. Louis, MO 63103

NON-EMERGENCY TELEPHONE	:	Product Stewardship, (314) 771-1800
Emergency telephone number	:	CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	PX-20487-B/BLACK THERMOSET PLASTISOL
Product code	:	FO20000072
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON HAZARDOUS INGREDIENTS

Components	CAS-No.	Weight %
OXIRANE, 2,2'-[(1-METHYLETHYLIDENE)BIS(4,1-P HENYLENEOXYMETHYLENE)]BIS-, HOMOPOLYMER	25085-99-8	1 - 5
Carbon black	1333-86-4	0.1 - 1

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole for health effects. Information provided on health effects of this product is based on the individual components. However, some vapors or contaminants may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. See sections 8 and 11 for special precautions.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Inhalation, Skin contact, Ingestion		
Acute exposure			
Inhalation	: Inhalation of airborne droplets may cause irritation of the respiratory tract.		
Ingestion	: May be harmful if swallowed.		
Eyes	: May cause eye/skin irritation.		
Skin	: Experience shows no unusual dermatitis hazard from routine handling.		



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.
	4. FIRST AID MEASURES
x 1 1	
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist, or in all cases of doubt, seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist, or in all cases of doubt, seek medical advice.
Eyes	: Rinse immediately with plenty of water for at least 15 minutes. If ey irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists see medical attention.
	5. FIRE-FIGHTING MEASURES
Flash point	: No data available.
Flammable Limits	
Upper explosion limit	: No data available.
Lower explosion limit	: No data available.
Autoignition temperature Suitable extinguishing media	Not applicable.Carbon dioxide blanket, dry powder, foam, Water spray.
Special Fire Fighting	: Fullface self-contained breathing apparatus (SCBA) used in positive
Procedures	pressure mode should be worn to prevent inhalation of airborne
	contaminants.
Unusual Fire/Explosion Hazards	: May emit Hydrogen Chloride (HCl) or Carbon Monoxide (CO) unde fire conditions.
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Soak up with inert absorbent material (e.g. sand, silica gel, acid binder universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods.
	7. HANDLING AND STORAGE



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Handling : Heat only in areas with appropriate exhaust ventilation. Processing fume condensates may contain combustible or toxic residue. Periodically clean hoods, ducts, and other surfaces to minimize accumulation of these materials. Storage : Keep containers dry and tightly closed to avoid moisture absorption and contamination. Store in a cool dry place. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Respiratory protection : Under normal handling conditions a respirator may not be required. Eye/Face Protection Eye/Face Protection : Safety glasses with side-shields. Hand protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Maal before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average Total dust, as carbon ACGIH Appearance : Viscous, Liquid Specific Gravity :: Not stablished Appearance Not established Protective Odor : BLACK Bulk density : Not established Protective : Not applicable Vapor density Not determined Bo	ion Number 1.0 sion Date 09/10/2002					Print I	Page 3 Date 11/6/2
Storage : Keep containers dry and tightly closed to avoid moisture absorption and contamination. Store in a cool dry place. SEXPOSURE CONTROLS / PERSONAL PROTECTION Respiratory protection : Under normal handling conditions a respirator may not be required. Eye/Face Protection : Safety glasses with side-shields. Hand protection : Protective gloves. Skin and body protection : Long sleeved clothing. Additional Protective :: Safety shoes. Measures : General Hygiene : Handle in accordance with good industrial hygiene and safety practic Considerations : Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average Total dust, as carbon OSHA ZI black 0.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black 3.5 mg/m3 PEL: Not established Odor : Eliquid Evaporation rate : Not established Opperaranc	Handling	fı P	ame condensates may eriodically clean hood	contain co ls, ducts, a	ombustible or	toxic resi	due.
Respiratory protection : Under normal handling conditions a respirator may not be required. Eye/Face Protection : Safety glasses with side-shields. Hand protection : Protective gloves. Skin and body protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Safety shoes. General Hygiene : Handle in accordance with good industrial hygiene and safety practic Considerations : Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Mean Mark Safety Protection Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average Total dust, as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI Spearance : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not applicable. Odor : ELACK Bulk density : Not applicable. Odor : Very fain	Storage	: K	eep containers dry an	d tightly c		d moisture	absorption
Eye/Face Protection : Safety glasses with side-shields. Hand protection : Protective gloves. Skin and body protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Safety shoes. General Hygiene : Handle in accordance with good industrial hygiene and safety practic Onsiderations Considerations : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Exposure time Exposure type List: Components Value Exposure time Total dust, as carbon ACGIH Carbon black 3.5 mg/m3 Time Weighted Average Total dust, as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black : : Not established Appearance : Viscous, Liquid Evaporation rate : Not established Color : BLACK Bulk density : Not determined Golor : Very faint Vapor pressure	8. 1	EXPOSURE	CONTROLS / PER	SONAL P	ROTECTIO)N	
Eye/Face Protection : Safety glasses with side-shields. Hand protection : Protective gloves. Skin and body protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Handle in accordance with good industrial hygiene and safety practic Onsiderations General Hygiene : Handle in accordance with good industrial hygiene and safety practic Onsiderations Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Exposure time Exposure type List: Components Value Exposure time Total dust, as carbon ACGIH Carbon black 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black : : Viscous, Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Color : BLACK Bulk density	Respiratory protection	: U	Inder normal handling	g condition	s a respirator	may not b	be required.
Hand protection : Protective gloves. Skin and body protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Safety shoes. General Hygiene : Handle in accordance with good industrial hygiene and safety practic Considerations : Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Stable Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average Total dust. as carbon ACGIH (TWA): black OSHA ZI black 3.5 mg/m3 PEL: Total dust. as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust. as carbon OSHA ZI black 0 Specific Gravity : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Color : BLACK Bulk density : Not determined Odor : Vost applicable Vapor pressure : Not determined Boiling Point: <td< td=""><td>Eye/Face Protection</td><td></td><td>-</td><td></td><td>-</td><td>·</td><td>-</td></td<>	Eye/Face Protection		-		-	·	-
Skin and body protection : Long sleeved clothing. Additional Protective : Safety shoes. Measures : Safety shoes. General Hygiene : Handle in accordance with good industrial hygiene and safety practic Onsiderations Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Diack : Somma in the weighted Average is the stabilistic of the stabilististic of the stabilististic of the stabilistic of the st	-						
Measures Engineering : Handle in accordance with good industrial hygiene and safety practic Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Ital: : Total dust, as carbon ACGIH (TWA): Carbon black : 3.5 mg/m3 PEL: Total dust, as carbon OSHA ZI black Carbon black : 3.5 mg/m3 PEL: Total dust, as carbon black Second class is the end of the exposure is the exposure is the exposure	-		-				
Considerations Wash hands before breaks and at the end of workday. Engineering measures : Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery. Exposure limit(s) : Heat only in areas with appropriate exhaust ventilation at machinery. Exposure limit(s) : Exposure time Exposure type List: Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average Total dust. as carbon ACGIH Carbon black 3.5 mg/m3 PEL: Total dust. as carbon OSHA ZI black 3.5 mg/m3 PEL: Total dust. as carbon OSHA ZI black 0 Specific Gravity Not established Appearance : Viscous, Liquid Specific Gravity Not determined Color : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible :		: S	afety shoes.				
appropriate exhaust ventilation at machinery. Exposure limit(s) Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average (TWA): Total dust. as carbon ACGIH Carbon black 3.5 mg/m3 PEL: Total dust. as carbon OSHA ZI OBLACK PHYSICAL AND CHEMICAL PROPERTIES Form : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Color : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible Immiscible Immiscible							afety practice
Components Value Exposure time Exposure type List: Carbon black 3.5 mg/m3 Time Weighted Average (TWA): Total dust. as carbon black ACGIH Carbon black 3.5 mg/m3 PEL: Total dust. as carbon black OSHA ZI Carbon black 3.5 mg/m3 PEL: Total dust. as carbon black OSHA ZI PHYSICAL AND CHEMICAL PROPERTIES Status Status Status OSHA ZI Form : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Color : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Melting point/range : Not applicable Vapor density : Not applicable. Water solubility : Immiscible Immiscible Immiscible Immiscible	Engineering measures					entilation.	Provide
Carbon black 3.5 mg/m3 Time Weighted Average (TWA): Total dust. as carbon black ACGIH Carbon black 3.5 mg/m3 PEL: Total dust. as carbon black OSHA ZI 9. PHYSICAL AND CHEMICAL PROPERTIES Form : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Odor : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Boiling point/range : Not applicable pH : Not applicable. Water solubility : Immiscible 10. STABILITY AND REACTIVITY	Exposure limit(s)						
Carbon black 3.5 mg/m3 Time Weighted Average (TWA): Total dust. as carbon black ACGIH Carbon black 3.5 mg/m3 PEL: Total dust. as carbon black OSHA ZI 9. PHYSICAL AND CHEMICAL PROPERTIES Form : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Odor : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Boiling point/range : Not applicable pH : Not applicable. Water solubility : Immiscible 10. STABILITY AND REACTIVITY	Components	Value	Exposure tim	e	Exposure	e type	List:
Carbon black 3.5 mg/m3 PEL: Total dust. as carbon black OSHA ZI black 9. PHYSICAL AND CHEMICAL PROPERTIES Form : Liquid Evaporation rate : Not established Appearance : Viscous, Liquid Specific Gravity : Not determined Color : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible 10. STABILITY AND REACTIVITY			Time Weighted Av		Total dust. a	is carbon	
Form: LiquidEvaporation rate: Not establishedAppearance: Viscous, LiquidSpecific Gravity: Not determinedColor: BLACKBulk density: Not applicable.Odor: Very faintVapor pressure: Not determinedMelting point/range: Not applicableVapor density: Not determinedBoiling Point:: Not applicablepH: Not applicable.Water solubility: Immiscible10. STABILITY AND REACTIVITY	Carbon black	3.5 mg/m3			Total dust. a	is carbon	OSHA Z1
Appearance:Viscous, LiquidSpecific Gravity:Not determinedColor:BLACKBulk density:Not applicable.Odor:Very faintVapor pressure:Not determinedMelting point/range:Not applicableVapor density:Not determinedBoiling Point::Not applicablepH:Not applicable.Water solubility:ImmiscibleImmiscibleImmiscible		9. PHYSIC	CAL AND CHEMIC	AL PRO	PERTIES		
Appearance:Viscous, LiquidSpecific Gravity:Not determinedColor:BLACKBulk density:Not applicable.Odor:Very faintVapor pressure:Not determinedMelting point/range:Not applicableVapor density:Not determinedBoiling Point::Not applicablepH:Not applicable.Water solubility:ImmiscibleImmiscibleImmiscible	Farm	. 1:	:	F		. N4	a ata b li a b a d
Color : BLACK Bulk density : Not applicable. Odor : Very faint Vapor pressure : Not determined Melting point/range : Not applicable Vapor density : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible Immiscible Immiscible							
Odor : Very faint Vapor pressure : Not determined Melting point/range : Not applicable Vapor density : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible Immiscible Immiscible							
Melting point/range : Not applicable Vapor density : Not determined Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible Immiscible Immiscible 10. STABILITY AND REACTIVITY			-				
Boiling Point: : Not applicable pH : Not applicable. Water solubility : Immiscible 10. STABILITY AND REACTIVITY							
Water solubility : Immiscible 10. STABILITY AND REACTIVITY	wiching point/range						
			iscible				
Stability : Stable.	Boiling Point:	: Imm	iscible				
	Boiling Point:			EACTIVI	TY		
	Boiling Point: Water solubility	10. 8	STABILITY AND R	EACTIVI	TY		



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Version Number 1.0 Revision Date 09/10/2002 Page 4 of 7 Print Date 11/6/2011

Hazardous Polymerization	:	Will not occur.
Conditions to avoid	:	Keep away from oxidizing agents and open flame. To avoid thermal decomposition, do not overheat.
Incompatible Materials	:	Incompatible with strong acids and oxidizing agents. Avoid contact with acetal homopolymers and acetal copolymers during processing.
Hazardous decomposition products	:	Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), hydrogen chloride (HCl), other hazardous materials, and smoke are all possible. Prolonged heating may result in product degradation. As a general rule of thumb, degradation begins to occur after one hour at 177 °C (350 °F), after 10 minutes at 204 °C (400 °F), and within 5 minutes at 232 °C (450 °F).

11. TOXICOLOGICAL INFORMATION

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

Toxicity Overview

This product contains the following components which in their pure form have the following characteristics:

CAS-No.	Chemical Name	Effect	Target Organ
25085-99-8	OXIRANE,	sensitizer	Skin.
	2,2'-[(1-METHYLETHYL		
	IDENE)BIS(4,1-PHENYL		
	ENEOXYMETHYLENE)		
]BIS-, HOMOPOLYMER		
1333-86-4	Carbon black	Systemic effects	Eyes, Respiratory system.

LC50 / LD50

This product contains the following components which in their pure form have the following toxicity data:

CAS-No.	Chemical Name	Route	Value	Species
1333-86-4	Carbon black	Oral LD50	> 15,400 mg/kg	rat
		Dermal LD50	> 3 gm/kg	rabbit

Carcinogenicity:

This product contains the following components which in their pure form have the following carcinogenicity data:

CAS-No.	Chemical Name	OSHA	IARC	NTP
1333-86-4	Carbon black	no	2B	no

IARC Carcinogen Classifications:

1 - The component is carcinogenic to humans.

2A - The component is probably carcinogenic to humans.

2B - The component is possibly carcinogenic to humans.



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Version Number 1.0 Revision Date 09/10/2002 Page 5 of 7 Print Date 11/6/2011

NTP Carcinogen Classifications:

1 - The component is known to be a human carcinogen.

2 - The component is reasonably anticipated to be a human carcinogen.

Additional Health Hazard Information:

Carbon black 1333-86-4 Carcinogenicity: Many inhalation toxicologists believe that the tumor response observed in the referenced rat studies is species specific and does not correlate to human exposure. However, the IARC evaluation in Monograph Volume 65, issued in April 1996 concluded that, "There is sufficient evidence in experimental animals for the carcinogenicity of carbon black". Based on this evaluation, along with their evaluation of inadequate evidence of carcinogenicity in humans, IARC's overall evaluation is that "Carbon Black is possibly carcinogenic to humans (Group 2B). Carbon Black has not been listed as a carcinogen by the National Toxicology Program (NTP) or the Occupational Safety and Health Administration (OSHA). The National Institute of Occupational Safety and Health (NIOSH) criteria document on carbon black recommends that only carbon black with PAH (polynuclear aromatic hydrocarbon) levels greater than 0.1% be considered suspect carcinogens.

Persistence and degradability	: Not readily biodegradable.			
Environmental Toxicity	: Environmental toxicity has not been established for this mixture as a whole.			
Bioaccumulation Potential	: No data available.			
Additional advice	: No data available.			
	13. DISPOSAL CONSIDERATIONS			
Product	: Where possible, recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.			
Contaminated packaging	ging : Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.			
	14. TRANSPORT INFORMATION			
U.S. DOT Classification	: Not regulated for transportation.			
ICAO/IATA	: Not regulated for transportation.			
IMO / IMDG	: Not regulated for transportation.			
	15. REGULATORY INFORMATION			



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Version Number 1.0	Page 6 of 7
Revision Date 09/10/2002	Print Date <i>11/6/2011</i>

US Regulations:

OSHA Status

: Classified as hazardous based on components.

TSCA Status

: All components of this product are listed on the TSCA inventory or are exempt.

US. EPA CERCLA Hazardous Substances (40 CFR 302)

Chemical Name	CAS-No.	% in Product	RQ for component	RQ for
				Mixture/Product
Xylenes (o-, m-, p-	1330-20-7	0.1746	100 lbs	57,274 LB
isomers)				

California Proposition : 65

: WARNING! This product contains a chemical known in the State of California to cause cancer.

Canadian Regulations:

WHMIS Classification : D2A

WHMIS Ingredient Disclosure List

CAS-No.
1333-86-4
8052-41-3
1330-20-7
557-05-1
95-63-6
1310-73-2
75-01-4

DSL

: Listed.

National Inventories:

Australia AICS	:	Listed.
China IECS	:	Listed.
Europe EINECS	:	Not determined.
Japan ENCS	:	Not determined.
Korea KECI	:	Not determined.



MATERIAL SAFETY DATA SHEET

PX-20487-B/BLACK THERMOSET PLASTISOL

Version Number 1.0 Revision Date 09/10/2002 Page 7 of 7 Print Date 11/6/2011

Philippines PICCS : Listed.

16. OTHER INFORMATION

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.