MATERIAL SAFETY DATA SHEET STAN-TONE HCC-31707# YELLOW

Version Number 1.0 Revision Date 07/22/2009 Page 1 of 5 Print Date 1/8/2012

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 8155 Cobb Center Drive, Kennesaw, GA 30152

Telephone Emergency telephone	:	Product Stewardship (770) 590-3500 x.3563 CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	STAN-TONE HCC-31707# YELLOW
Product code	:	FO20022559
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON REGULATED INGREDIENTS

There are no known hazardous components above regulatory thresholds in this product.

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole for health effects. Information provided on health effects of this product is based on the individual components. However, some vapors or contaminants may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. See sections 8 and 11 for special precautions.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Inhalation, Skin contact, Ingestion
Acute exposure	
Inhalation	: Inhalation of airborne droplets may cause irritation of the respiratory tract.
Ingestion	: May be harmful if swallowed.
Eyes	: May cause eye and skin irritation.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.
Medical Conditions Aggravated by Exposure:	: None known.
	4. FIRST AID MEASURES

PolyOne.

MATERIAL SAFETY DATA SHEET STAN-TONE HCC-31707# YELLOW

Inhalation : Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases of doubt seek medical advice. Ingestion : Do not induce vomiting without medical advice. Seek medical attention if necessary. Eyes : Rinse immediately with plenty of water for at least 15 minutes. If ey irritation persists, seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Skin : Move to data available Flash point : no data available Flammable Limits : no data available Lower explosion limit : no data available Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO, oxides of nitrogen (NOX), other hazardous materials, and smoke are all possible. Brazards : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Methods for cleaning up : Soak up with inert absorbent material (ion Number 1.0 sion Date 07/22/2009	Page 2 Print Date 1/8/2
overheating or combustion. When symptoms persist or in all cases or doubt seek medical advice. Ingestion : Do not induce vomiting without medical advice. Seek medical attention if necessary. Eyes : Rinse immediately with plenty of water for at least 15 minutes. If ey irritation persists, seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Flash point : no data available Flammable Limits Upper explosion limit : Upper explosion limit : no data available Autoignition temperature : Not applicable Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES : Environmental precautions : : Wear appropriate personal protection during c		
attention if necessary. Eyes : Rinse immediately with plenty of water for at least 15 minutes. If ey irritation persists, seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Skin : Inter-FIGHTING MEASURES Flash point : no data available Flammable Limits : no data available Upper explosion limit : no data available Sutable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible. 6 ACCIDENTAL RELEASE MEASURES : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : The product should not be released into the environment. Methods for cleaning up : Soak up with inert absorbent material (e.g. sand, silica gel, ac	Inhalation	overheating or combustion. When symptoms persist or in all cases of
irritation persists, seek medical attention. Skin : Wash off with soap and plenty of water. If skin irritation persists seek medical attention. Skin : FIRE-FIGHTING MEASURES Flash point : no data available Flammable Limits Upper explosion limit Upper explosion limit : no data available Autoignition temperature : Not applicable Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOX), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES Personal precautions : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Methods for cleaning up : Soak up with inert absorbent material (e.g. sand, slica gel, acid binder, universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods. 7. HANDLING AND STORAGE Handling :	Ingestion	•
seek medical attention. 5. FIRE-FIGHTING MEASURES Flash point : no data available Flammable Limits Upper explosion limit : no data available Lower explosion limit : no data available Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES Personal precautions : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Methods for cleaning up : Soak up with inert absorbent material (e.g. sand, silica gel, acid binder, universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods. 7. HANDLING AND STORAGE * Handling : Heat only in areas with appropriate exhaust ventilation. Prolonged heating may result in product degradation.	Eyes	
Flash point : no data available Flammable Limits Upper explosion limit : no data available Autoignition temperature : Not applicable Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting : Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion : Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES Personal precautions : Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions : The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Methods for cleaning up : Soak up with inert absorbent material (e.g. sand, silica gel, acid binder, universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods. 7. HANDLING AND STORAGE Handling : Heat only in areas with appropriate exhaust ventilation. Prolonged heating may result in product degradation. Storage : Keep containers dry and tightly closed to avoid moisture absorption	Skin	
Flammable Limits Upper explosion limit : no data available Autoignition temperature :: Not applicable Suitable extinguishing media : Carbon dioxide blanket, Water spray, Dry powder, Foam. Special Fire Fighting :: Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Unusual Fire/Explosion :: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOX), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES Personal precautions :: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. Environmental precautions :: The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Methods for cleaning up :: Soak up with inert absorbent material (e.g. sand, silica gel, acid binder, universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS for proper disposal methods. 7. HANDLING AND STORAGE Handling :: Heat only in areas with appropriate exhaust ventilation. Prolonged heating may result in product degradation. Storage : Keep containers dry and tightly closed to avoid moisture absorption		5. FIRE-FIGHTING MEASURES
Upper explosion limit Lower explosion limit: no data available : no data availableAutoignition temperature Suitable extinguishing media: Not applicable : Carbon dioxide blanket, Water spray, Dry powder, Foam.Special Fire Fighting Procedures: Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne 	Flash point	: no data available
7. HANDLING AND STORAGE Handling : Heat only in areas with appropriate exhaust ventilation. Prolonged heating may result in product degradation. Storage : Keep containers dry and tightly closed to avoid moisture absorption	Upper explosion limit Lower explosion limit Autoignition temperature Suitable extinguishing media Special Fire Fighting Procedures Unusual Fire/Explosion Hazards Personal precautions Environmental precautions	 no data available Not applicable Carbon dioxide blanket, Water spray, Dry powder, Foam. Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible. 6. ACCIDENTAL RELEASE MEASURES Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls. The product should not be allowed to enter drains, water courses or the soil. Should not be released into the environment. Soak up with inert absorbent material (e.g. sand, silica gel, acid binder, universal binder, sawdust). Package all material in appropriate container for disposal. Refer to Section 13 of this MSDS
heating may result in product degradation. Storage : Keep containers dry and tightly closed to avoid moisture absorption		7. HANDLING AND STORAGE
	Handling	
	Storage	

PolyOne.

MATERIAL SAFETY DATA SHEET STAN-TONE HCC-31707# YELLOW

Version Number 1.0 Revision Date 07/22/2009 Page 3 of 5 Print Date 1/8/2012

0. E21	POSURE CONTROLS/PE	RSONAL PROTECTION
Respiratory protection	: Under normal handl	ing conditions a respirator may not be required.
Eye/Face Protection	: Safety glasses with	side-shields
Hand protection	: Protective gloves	
Skin and body protection	: Long sleeved clothi	ng
Additional Protective Measures	: Safety shoes	
General Hygiene Considerations		ce with good industrial hygiene and safety ds before breaks and at the end of workday.
Engineering measures		vith appropriate exhaust ventilation. Provide ventilation at machinery.
Exposure limit(s)		
There are no known hazardou	us components above regula	tory thresholds in this product.
9.	. PHYSICAL AND CHEM	IICAL PROPERTIES
Form	· liquid	Evaporation rate · Not established
	: liquid : liquid, Viscous liquid	Evaporation rate : Not established Specific Gravity : Not determined
	: liquid, Viscous liquid	Evaporation rate: Not establishedSpecific Gravity: Not determined
Appearance	: liquid, Viscous liquid dispersion	Specific Gravity : Not determined
Appearance Colour	liquid, Viscous liquid dispersionYELLOW	Specific Gravity: Not determinedBulk density: Not applicable
Appearance Colour Odour	 liquid, Viscous liquid dispersion YELLOW very faint 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determined
Appearance Colour Odour Melting point/range	 liquid, Viscous liquid dispersion YELLOW very faint not applicable 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determinedVapour density: Heavier than air.
Appearance Colour Odour Melting point/range Boiling Point:	 liquid, Viscous liquid dispersion YELLOW very faint not applicable not applicable 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determined
Appearance Colour Odour Melting point/range Boiling Point:	 liquid, Viscous liquid dispersion YELLOW very faint not applicable 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determinedVapour density: Heavier than air.
Appearance Colour Odour Melting point/range Boiling Point:	 liquid, Viscous liquid dispersion YELLOW very faint not applicable not applicable 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determinedVapour density: Heavier than air.pH: Not determined
Appearance Colour Odour Melting point/range Boiling Point: Water solubility	 liquid, Viscous liquid dispersion YELLOW very faint not applicable not applicable immiscible 	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determinedVapour density: Heavier than air.pH: Not determined
Form Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization	 liquid, Viscous liquid dispersion YELLOW very faint not applicable not applicable immiscible 10. STABILITY AND	Specific Gravity: Not determinedBulk density: Not applicableVapour pressure: Not determinedVapour density: Heavier than air.pH: Not determined
Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization	 : liquid, Viscous liquid dispersion : YELLOW : very faint : not applicable : not applicable : immiscible 10. STABILITY AND : Stable : Will not occur. 	Specific Gravity : Not determined Bulk density : Not applicable Vapour pressure : Not determined Vapour density : Heavier than air. pH : Not determined PREACTIVITY : Not determined idizing agents and open flame. To avoid thermal
Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization Conditions to avoid	 liquid, Viscous liquid dispersion YELLOW very faint not applicable not applicable immiscible 10. STABILITY AND Stable Will not occur. Keep away from ox decomposition, do r 	Specific Gravity : Not determined Bulk density : Not applicable Vapour pressure : Not determined Vapour density : Heavier than air. pH : Not determined PREACTIVITY : Not determined idizing agents and open flame. To avoid thermal
Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability	 : liquid, Viscous liquid dispersion : YELLOW : very faint : not applicable : not applicable : immiscible 10. STABILITY AND : Stable : Will not occur. : Keep away from ox decomposition, do r : Incompatible with s : Carbon dioxide (CC) 	Specific Gravity : Not determined Bulk density : Not applicable Vapour pressure : Not determined Vapour density : Heavier than air. pH : Not determined OREACTIVITY : idizing agents and open flame. To avoid thermal not overheat.

PolyOne.

MATERIAL SAFETY DATA SHEET STAN-TONE HCC-31707# YELLOW

Version Number 1.0 Revision Date 07/22/2009 Page 4 of 5 Print Date 1/8/2012

There are no known hazardous components above regulatory thresholds in this product.

	12. ECOLOGICAL INFORMATION
Persistence and degradability	: Not readily biodegradable.
Environmental Toxicity	: Environmental toxicity has not been established for this mixture as a whole.
Bioaccumulation Potential	: no data available
Additional advice	: no data available
	13. DISPOSAL CONSIDERATIONS
Product	: Where possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification	: Refer to specific regulation.
ICAO/IATA	: Refer to specific regulation.
IMO / IMDG (maritime)	: Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: There are no known hazardous components above regulatory thresholds in this product.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.
US. EPA CERCLA Hazardous	Substances (40 CFR 302)
not applicable	

MATERIAL SAFETY DATA SHEET STAN-TONE HCC-31707# YELLOW

Version Number 1.0 Revision Date 07/22/2009 Page 5 of 5 Print Date 1/8/2012

California Proposition : Not applicable 65

SARA Title III Section 302 Extremely Hazardous Substance

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

SARA Title III Section 313 Toxic Chemicals:

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

Canadian Regulations:

National Pollutant Release Inventory (NPRI)

not applicable

WHMIS Classification	:	Not controlled.
DSL	:	All components of this product are on the Canadian Domestic Substances List (DSL) or are exempt.
National Inventories:		
Australia AICS	·	Listed

16. OTHER INFORMATION				
Philippines PICCS	:	Listed		
Korea KECI	:	Listed		
Japan ENCS	:	Listed		
Europe EINECS	:	Listed		
China IECS	:	Listed		
Australia AICS	•	Listed		

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.